Smart Construction Pilot v1.0.04.1 Updates



The design surface cross section line is displayed tilted in Section View.

Fixed the logic to create a design surface cross section line in Section View.

Changed the refresh rate of numerical values on the guidance screen.

The refresh rate changed from 10Hz to 3Hz which makes it much easier to check the numerical values.

For specific Ntrip Casters, mount point information cannot be acquired.

The Ntrip Client is updated from Rev 1 to Rev 2.

Projection data cannot be acquired in case of a specific projection.

For projections that need a grid shift binary there was an issue that the projection data could not be acquired from the server correctly.