## Smart Construction Retrofit v1.7.2 Update details



## **Swing/Offset boom calculation process change**

## The calculation process for swing boom and offset boom specifications has been corrected.

- $\cdot$  Contains fixes for controller FW v1.7.1 and earlier.
- For information on how to update the controller FW, please refer to the article on the support website.
  (Europe / US / Australia / Asia)

## Important matter

- When using machine guidance function with swing boom and offset boom, be sure to **update controller FW to v1.7.2 or higher**.
- When using machine guidance function with swing boom, be sure to **update tablet app to v1.0.04.2 or higher**.
- Offset boom is not yet supported as of tablet app v1.0.04.2
  - (The supported version and release date will be notified in the tablet app release notes.)