## Smart Construction Retrofit v1.5.8 Update







## **EARTHBRAIN** Controller for AT03 model does not FIX stably

A problem with the controller model SCRF00AT03, displayed "GNSS Heading Unusable" and could not be used stably, has been addressed in v1.5.8.


GNSS is Fixed RTK but "GNSS Heading Unusable" does not disappear and stable operation is not possible.





## Important

For controllers with PRODUCT NAME "SCRF00AT03", please update the FW using Pilot UPD. Initialization of the configuration file is not required.



\*This release is a bug fix and does not include CMR/CMR+ support.